

Dynamic Elevator Control Corp.


1840 NW 95th Ave

Miami, FL 33172

+13055972588

info@dynamic-elevator.com

www.dynamic-elevator.com



Proposal

ADDRESS

Verabella Falls Condominium Serial 68848

8205 SW 152nd Ave

Miami, FL 33193

PROPOSAL

10656

DATE

10/14/2026

SERIAL

68848



Repairs 4,785.00

- Place the elevator at a medium level from the first floor and suspend the cab structure by holding it and dismantling it from the floor.
- Remove all flooring, platform and metal sheet underneath.
- Furnish and Install New Elevator Platform Constructed of 3/4-inch Marine-Grade/ Fire Rated Plywood.
- Furnish and Install Fire Rated Metal Sheet underneath of platform as required by ASME A17.1 2019.
- Furnish and Install New Rubber Flooring.
- Furnish and install New Cab Sill
- Assemble back the cab structure and put the elevator back to work.
- Estimated time of work: 1 week

Permit and inspection fees are the client's responsibility.

NOTES:

- * Elevator must stay out of service until a passing inspection report closes the permit. Dynamic Elevator Control Corp. will not be liable for possible damage to the Cabin due to termites.
- * If we find other deficiencies that are preventing the elevator from returning back to service, a separate estimate with the necessary work will be sent over.

You agree to pay the Dynamic Elevator Control Corp. the amount specified above which will cover the costs of labor and material. Should it be necessary to collect any of the money due to us under this agreement with you, through an attorney, then you shall pay all costs of collection including reasonable attorney's fee. There shall be no liability for delays due to causes beyond our control. Accounts in arrears thirty (30) days will be assessed a monthly service charge of 1.5%

SUBTOTAL	4,785.00
TAX	0.00
TOTAL	\$4,785.00

Accepted By:

Accepted Date:

For detailed information regarding the warranty and terms & conditions, please visit
<https://dynamic-elevator-control.com/terms-conditions/>