


Verabella Falls Condominium – Camera System Evaluation and Recommendation



Miami Premium Security Llc <messenger@messaging.squareup.com>

To ○ Marisabel



10/1/2026

Dear Marisabel,

Thank you for the opportunity to walk the Verabella Condominium and for discussing the requested work. We have completed a site visit to review the installation of cameras in the dumpster areas and the removal/relocation of the camera boxes from the elevator rooms, as requested.

After our evaluation, we recommend that the original installation company perform this work. Our recommendation is based on the following:

- **Warranty Considerations** – Using another company may void the existing warranty on the system.
- **Existing System Knowledge** – The original installer is familiar with the current cable configuration, equipment, and system setup, which helps ensure the work is completed correctly and without disrupting the existing system.
- **Liability** – We will not be responsible for the existing installation, and we cannot assume any responsibility for issues that may arise from modifying a system installed by another contractor.

Our goal is to ensure the condominium's security system continues to operate properly and remains covered under warranty. For these reasons, we advise coordinating directly with the original installation company to perform the requested changes.

Please let us know if you have any questions or need further clarification.

Thank you,

Miami Premium Security Llc

messenger@messaging.squareup.com